



What is Wrong with this Picture?
Construction Safety

Construction Safety – Answer Key




- The foam-style earplug isn't adequate protection against the noise from the jackhammer.
- The worker is wearing a ball cap under his hard hat, which could impact the fit.



- The worker has an unsafe and wide stance with his back foot on top of a hose and his left foot on the wall.
- The worker isn't using his equipment correctly. His foot is too close to the jackhammer.
- The hoses are a tripping hazard.



- Various lumber is laying around the worksite instead of being stored in one place. This is a tripping hazard



- The worker should not be trying to listen to his cell phone. Not only is the distraction a hazard, but he's removed his hearing protection to listen which can result in hearing loss.



- There's some unidentified bags in the background which may contain food. Food doesn't belong next to a bucket of chemicals.
- The saw horse is unstable and is missing a leg.




- Foam-style earplugs aren't adequate protection against the noise from the jackhammer and other work site noise.
- The worker isn't wearing safety goggles.
- His safety vest is open and tangled enough that the reflectors are difficult to see.
- The worker is wearing a ball cap under his hard hat, which could impact the fit.
- He is distracted by the other worker with the cell phone while using a buzz saw



- The worker has poorly tied shoes



- The scaffolding leaning in the background isn't secured.



1.	
2.	
3.	
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	
12.	
13.	
14.	
15.	
16.	
17.	
18.	